



Rev.02-11-2020

Rear Kick Back Exposed Wood Cover

Part No. **PPP-RKBC**

pkg of 1



Cover gouged wood and holes to prevent further damage.
Cover undamaged kickbacks to prevent damage from occurring.

UHMW Cover can be easily cut and trimmed to suit individual kick back situations.

Remove upper shaker frame and mount Cover behind rear kick back plate to span pin-pass-by area 2 inches below wood damage.

Do not secure into damaged wood or near pin-pass-by areas. Use caution to not overly tighten screws to prevent their breakage.

Cushion can usually be maneuvered to allow uppermost Cover securing. Exact screw position, or pattern unimportant, if provided holes are inaccessible.



Rev.02-11-2020

Rear Kick Back Exposed Wood Cover

Part No. **PPP-RKBC**

pkg of 1



Cover gouged wood and holes to prevent further damage.
Cover undamaged kickbacks to prevent damage from occurring.

UHMW Cover can be easily cut and trimmed to suit individual kick back situations.

Remove upper shaker frame and mount Cover behind rear kick back plate to span pin-pass-by area 2 inches below wood damage.

Do not secure into damaged wood or near pin-pass-by areas. Use caution to not overly tighten screws to prevent their breakage.

Cushion can usually be maneuvered to allow uppermost Cover securing. Exact screw position, or pattern unimportant, if provided holes are inaccessible.



Rev.02-11-2020

Rear Kick Back Exposed Wood Cover

Part No. **PPP-RKBC**

pkg of 1



Cover gouged wood and holes to prevent further damage.
Cover undamaged kickbacks to prevent damage from occurring.

UHMW Cover can be easily cut and trimmed to suit individual kick back situations.

Remove upper shaker frame and mount Cover behind rear kick back plate to span pin-pass-by area 2 inches below wood damage.

Do not secure into damaged wood or near pin-pass-by areas. Use caution to not overly tighten screws to prevent their breakage.

Cushion can usually be maneuvered to allow uppermost Cover securing. Exact screw position, or pattern unimportant, if provided holes are inaccessible.